

Oil Field Environmental Incident Summary

Incident: 20160523101740 **Date/Time of Notice:** 05/23/2016 10:17

Responsible Party: ENDURO OPERATING, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: NORTH BRANCH 22X-35

Field Name: NORTH BRANCH

Well File #: 12550

Date Incident: 5/22/2016 **Time Incident:** 12:10

Facility ID Number:

County: MCKENZIE

Twp: 148

Rng: 102

Sec: 35

Qtr:

Location Description:

Submitted By: Rodney Conway

Received By:

Contact Person: Rodney Conway
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 5 Mile

Distance Nearest Water Well: 5 Mile

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Oil removed from tank. Roustabouts will repair and clean up and haul to IHD.

Wastes Disposal Location: IDH land fill.

Agencies Involved:

Updates

Date: 5/23/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, was contained within diking according to the report. NDIC retains oversight.